
15307
7837
7425
13881
15993
1501
TO
LOBBY
ENTRY
CHECK EXPANSION JOINT RUNNING THROUGH.
Avoid entry below the shaft as discussed last
MAINTAIN LINE. AS PER TYP. FLOOR
TYPICAL FLOOR LINE TO BE MAINTAINED @ AMENITY LEVEL. FSI cannot increase here; as per Liaison.
SLAB SHOULD BE @ BEAM BOTTOM.
ACME OZONE AMENITY LVL PLAN. 16/8/2022.