KAPADIA ASSOCIATES
DESIGN LLP

112 – 114, Peninsula Center, Dr. S. S. Rao Road, Off S. S. Rao Road, Parel East, Mumbai 400012. Tel.: 6660 2838 Fax: 6660 2844


STATUS REPORT


To Venkatesh K. Date 04-Dec-2014.

From **Ashok Sandipamu.**


Project **Palava – Sector 03.**

Subject 2nd floor slab checking for Primia J wing conducted on 03-Dec-2014.

Sr. no	Area / Location	Images	Comments\ Observations	Recommendation
1	Toilets Sleeves @ units 1, 2, 3, 4, 5&6.		Toilets sleeves are Work in progress in all units.	To be provide as per drawings.
2	Utility Sunk @ units 1, 2, 3, 4, 5&6.		Side shuttering is in progress in all units	To be rectified as per drawings.

Sr. no	Area / Location	Images	Comments\ Observations	Recommendation
3	200X200 mm cutout @ staircase 02		200X200 cutout near firefighting duct to be provided	To be provide as per cut out drawings.
4	Terrace slab @ unit 02		200X200 cut out alignment should done properly	To be provide as per cut out drawings.

Sr. no	Area / Location	Images	Comments\ Observations	Recommendation
5	Service slab chajja @ unit 3&4.		Chajja in service area to be provided	To be provide as per drawings.
6	Toilet alignment @ all units		Alignment in toilets are in progress	To be provide as per drawings.

Sr. no	Area / Location	Images	Comments\ Observations	Recommendation
	Toilet beam @unit 3&4.		-50 mm along Y-Y directions.	To be rectified as per drawings

Note:-Site to proceed with RCC works after addressing the comments.

Checked & observed on site by:-

Gauri Kulkarni - Lodha.

Jayesh - Lodha.

Ashok Sandipamu - KAPL.